

Energy Efficient Investments ENE Energy Advisors

Raymond Performance Contract Update







Facility Preliminary Take Away

- 1. Raymond HS Boiler Room is at end of life
- 2. Raymond MS Boiler room has oil and is nearing end of life
- 3. Portions of the district school lack code ventilation
- 4. Controls are being upgraded at HS using ESSER
- 5. Lights are fluorescent and can be upgraded to LED
- 6. Building has room for improvement on envelope
- 7. Most of school does not have air conditioning
- 8. Ventilation Units are nearing end of life
- 9. Solar combined with these projects can improve payback



History

- EEI has been working with Raymond Schools since 2016 and worked with facilities to reduce energy consumption and improve controls
- EEI is has met with SAU to review a plan to reduce energy consumption and replace aging infrastructure
- Solar grants combined with replacing oil systems can drastically reduce consumption



2 HS Ventilation Units Original to building





Oil Boilers at Middle School and HS





LED Options





Fuel Options

- 1. Remain on oil
- 2. Propane
- 3. Wood Heating





Next Steps

- 1. Work on leasing options
- 2. If we move forward decide of Elementary School Should be included
- 3. Determine timeline for final budget numbers



Questions & Answers

Please email follow-up questions to Mike Davey at

MDavey@EEIServices.com