

Recommendation	
Johnson Controls	

**SCHOOL ADMINISTRATIVE UNIT 33**

## BID SUMMARY SHEET

<b><i>SCHOOL BOARD POLICY</i></b>	
<b>Policy:</b>	
<b>Bid Requirement:</b>	<b>\$ 9,999.99</b>

Bid Process: Advertisements

**Request for Quote**  
RHS Fire Pump Replacement

**Closed**  
4/29/20

@  
1:00 PM

**# Bid Proposals Received:** 2

CIP / Capital Reserve Fund

\$30,000.00

2019-2020

**Name of Vendor / Contractor**

**Required Bid Documents**  
General Company Information  
Quotation Form  
Proposal Contract Person

### Bid Amounts

Contracted Amount

[illegible]

According to both bids, there may be an additional cost if they have to re-align because there may not be enough room for the engine to be moved to get a proper alignment. So another day may be needed to align the engine to a proper location for align the mounting holes properly. We are asking for an additional \$5,000 in case this process needs to be done.